

PORT NOTICE

Safe Pilot Transfer Arrangements

PN/009

OPS-LEG-09

General Manager Operations

Partnering in growth, connecting people and supporting potential

PREFACE

This Port Notice is issued pursuant to Section 57 of the *Ports Management Act 2015 (NT)*.

SCOPE

This Port Notice applies to pilot embarkation and disembarkation within the gazetted Port of Darwin limits as detailed in Figure 1.



Figure 1 – Darwin Port Limits

DEFINITIONS

Term	Definition
AMSA	Australian Maritime Safety Authority
IMO	International Maritime Organisation
IMPA	International Marine Pilots Association
SOLAS	Safety of Life at Sea

Partnering in growth, connecting people and supporting potential

DIRECTION

Pilot Transfer Arrangement (All Vessels Required to Take a Pilot within the Compulsory Pilotage Area)

Safe pilot transfer arrangements must be carried out in accordance with SOLAS Regulation V/23 and IMO Resolution A.1045(27) *Minimum Standards for Equipment Installed & Arrangements for Pilot Transfers on Ships* set out in Annexure A, ISO 799-1:2019 and supplementary standards ISO 799-2:2021 and ISO 799-3:2022.

From 01 June 2023, Darwin Port will align our enhanced pilot ladder assurance requirements with the national framework developed by the Ports Australia Operations Working Group.

Owners, masters and occupiers of vessels must submit to the appointed vessel's agent and to Darwin Port Harbour Control the "Certificate of Manufacture", completed *Safe Pilot Ladder Securing and Boarding Arrangement Master's Declaration for the Port of Darwin*, set out in Annexure B and photographs of the stanchions and deck securing arrangements no later than twenty-four (24) hours prior to arrival at the Port of Darwin.

Darwin Port will not accept pilot ladders that are older than thirty months (30) months from the date of manufacture and man ropes that are older than twelve (12) months from the date of manufacture from a ship's chandlery.

Vessel operators are to assess and provide ship specific instructions to vessel's crews regarding storage and care of pilot ladders and man ropes. Industry guidance regarding care of manila ropes/manufacturer's instructions must be referred to when preparing the above instructions. Dedicated and protected spaces on board must be identified.

Vessels that Adopt the Use of Manropes

Maximum permitted age of manropes used with pilot ladders is twelve (12) months. The period of 12 months is to commence from the date the manrope was manufactured. A new manrope must not be cut out from an existing coil onboard that is more than 12 months old.

Vessels with a Freeboard Greater than Nine (>9) Metres During Pilot Disembarkation (Supplemental)

Vessels that arrive or depart with their freeboard in excess of nine (9) metres and that are required to assemble safe pilot boarding arrangements in the combination ladder format for disembarkation and must have the manropes tucked through the ladder steps 1.5 metres above the lower platform horizontal in accordance with Annexure C of this Port Notice.

REVIEW STATEMENT

This Port Notice will be reviewed biennially by the Port Management Officer.

REFERENCES

- SOLAS Regulation V/23 Minimum Standards for Equipment Installed & Arrangements for Pilot Transfers on Ships"
- IMO Resolution A.1045(27) "Pilot Transfer Arrangements"
- AMSA Marine Notice 03/2019, "Pilot Transfer Arrangements"
- ISO 799:2019 "Ships and Marine Technology – Pilot Ladders"
- ISO 799-2:2021 "Ships and Marine Technology — Pilot Ladders — Part 2: Maintenance, Use, Survey, and Inspection"

Partnering in growth, connecting people and supporting potential

- ISO 799-3:2022 “Ships and Marine Technology — Pilot Ladders — Part 3: Attachments and Associated Equipment”
- IMO/IMPA “Pilot Ladder Poster”
- Port Management Act 2015 (NT)
- Work Health and Safety (National Uniform Legislation) Act 2011 (NT)

REQUIRED BOARDING ARRANGEMENTS FOR PILOT







INTERNATIONAL MARITIME ORGANIZATION

In accordance with SOLAS Regulation V/23 & IMO Resolution A.1045(27)

INTERNATIONAL MARITIME PILOTS' ASSOCIATION

H.Q.S. "Wellington" Temple Stairs, Victoria Embankment, London WC2R 2PN Tel: +44 (0)20 7240 3973 Fax: +44 (0)20 7210 3518 Email: office@impahq.org

This document and all IMO Pilot-related documents are available for download at: <http://www.impahq.org>



ANNEXURE B**Safe Pilot Ladder Securing and Boarding Arrangement Master's Declaration for the Port of Darwin****Compliance:**

Port Notice PN/009 (Safe Pilot Transfer Arrangements), Darwin Port requires the owner, master or occupier of a vessel to comply with the safe pilot boarding access arrangements in accordance with the following rules and regulations:

- SOLAS Regulation V/23 "Minimum Standards for Equipment Installed & Arrangements for Pilot Transfers on Ships"
- IMO Resolution A.1045(27) "Pilot Transfer Arrangements"
- AMSA Marine Notice 03/2019, "Pilot Transfer Arrangements"
- ISO 799:2019 "Ships and Marine Technology – Pilot Ladders"
- ISO 799-2:2021 "Ships and Marine Technology – Pilot Ladders – Part 2: Maintenance, Use, Survey, and Inspection"
- ISO 799-3:2022 "Ships and Marine Technology – Pilot Ladders – Part 3: Attachments and Associated Equipment"
- IMO/IMPA "Pilot Ladder Poster"

Darwin Port requires the master of any vessel arriving at the Port of Darwin to declare that the design, procurement, installation and ongoing maintenance of the pilot ladder is in accordance with the above rules and regulations. Pilot ladders must not be older than thirty (30) months from the fabrication date and manropes must be no older than twelve (12) months.

Separately, Darwin Port requires the owner, master or occupier of a vessel to provide the following supplemental information:

- "Certificate of Manufacturer" or photograph of the manufacturer's plate for the pilot ladder
- Photographs of the condition of the stanchions and foundation brackets
- Confirmation of the procurement of pre-manufactured manropes that are less than twelve (12) months old or;
- If manropes are manufactured from a coil of approved rope that this was within the last twelve (12) months.

Finally, vessels that arrive or depart the Port of Darwin with their freeboard more than nine (9) metres and that are required to assemble safe Pilot boarding arrangements in the combination ladder format for disembarkation, must have the manropes tucked through the ladder steps 1.5 metres above the lower horizontal platform of the accommodation ladder in accordance with Annexure C of Port Notice [PN/009](#).

Declaration:

I, the Master of the LNGC/MT/MV/SS/FV/SV _____, declare that the pilot ladder has been erected in accordance with the above rules and regulations and that the pilot ladder in use for this port call is not older than 30 months from the fabrication date of the pilot ladder. Pilot ladder manropes are less than 12 months old.

Pilot Ladder Manufactured Date: _____

Pilot Ladder Supplier: _____


Master's Signature: _____ Date: _____

Note: Please complete this form and email this page and the copy of the Pilot Ladder Certificate to; HarbourControl@darwinport.com.au and Ship's Agent **24 hours prior to Arrival or Departure from Darwin Port**

Partnering in growth, connecting people and supporting potential

ANNEXURE C

Photograph Illustrating the Combination Ladder with the Manropes tucked through the side ropes ~1.5 metres above the horizontal platform of the accommodation ladder



PETER DUMMETT
Port Operator
Darwin Port
21st October 2023