

6 January 2022

Mr Graeme Richmond  
Owner F.V. Marijka

## F.V. MARIJKA – DIRECTION

On 1 December 2021 your vessel F.V. Marijka was temporarily secured to a mooring in the Small Boat Anchorage within the Port of Darwin at approximate latitude 12° 28' .474S longitude 130° 51' .790E. On 2 December 2021 we issued a direction to you under subsection 39(3) of the *Ports Management Act 2015 (NT) (PMA)* to immediately move your vessel to a safe and secure location however we note that you failed to act on this direction.


On 25 December 2021 the F.V. Marijka sunk at the mooring referred to above. The F.V. Marijka remains in such a condition that it is likely to cause damage to, endanger or obstruct the passage of navigation or use of the port by vessels. Consequently, in accordance with section 41(2) of the PMA, Darwin Port directs you, as owner of the vessel, to:

- remove it from the port; or
- move it to another place within the port; or
- repair it and make it safe; or
- destroy it and all fittings and equipment on board.

This direction must be complied with by 24 January 2022. A failure to comply with this direction within the required timeframe is a strict liability offence under the PMA.

Should you fail to comply with this direction within the required timeframe Darwin Port may carry out the work necessary to comply with this direction and recover the cost of doing so from you as a debt due and payable in accordance with section 41(9) of the PMA.

Sincerely

A handwritten signature in blue ink, appearing to read 'IAN NIBLOCK', written over a large, stylized blue scribble.

IAN NIBLOCK  
Port Management Officer